Inter Dyne Systems, Inc.

Date: April 8, 2014

Report No.: 101534612GRR-001

Page 12 of 18

## SPECIAL WALL MOUNTED PEG LOAD TEST:

Dates Tested:

3/18/14

Product Condition:

New

Test Procedure: Test Method:

Mount the pegs to the wall per manufacturer's

instructions and load the pegs until failure

Number of Samples Tested:

Ten (10)

Acceptance Level:

No acceptance level given

## Results:

Sample Number	Ultimate Static Load	Description of Results
1	160	Peg mount stripped through hole
2	160	Peg mount stripped through hole
3	160	Peg mount stripped through hole

Sample Number	155lbs Static Load	Description of Results
1	155lbs Static Load	Held the load
2 `	155lbs Static Load	Held the load
3	150lbs Static Load	Peg mount stripped through hole
4	155lbs Static Load	Held the load
5	150lbs Static Load	Peg mount stripped through hole
6	155lbs Static Load	Held the load
7	155lbs Static Load	Held the load
8	155lbs Static Load	Held the load
9	150lbs Static Load	Peg mount stripped through hole
10	155lbs Static Load	Held the load


The samples are to be evaluated by InterDyne Systems. Refer to the following page for photographs.

Inter Dyne Systems, Inc. Date: April 8, 2014

Report No.: 101534612GRR-001 Page 13 of 18



Peg Static Load



Failure Examples